



C368 SOFTWARE UPDATE NOTICE

MCU 2.02 VFD 2.01 BT 1.26

MCU 2.02 VFD 2.01 BT 1.26 and their future iterations are applicable only for the following serial numbers

- **From** H217C368G27634 **excluding** H217C368G27637, ...27634, ...27659, ...27636 and ...27635

IMPORTANT!

- **DO NOT load MCU 1.75 VFD 1.22 BT 1.26 to units from H217C368G27634.** If MCU 1.75 VFD 1.22 are inadvertently loaded to units from H217C368G27634 (including the exclusions mentioned above), the front panel display may go dark. If this happens, follow the Guidelines on how to recover front panel display when wrong firmware is installed (Service Hint - C368_C388-HINT2021-01).