D3045 SOFTWARE RELEASE NOTES

MCU 2.07

MCU 2.07 is applicable only up to the following serial number

- Up to H213D304505800

IMPORTANT!
Do not to load MCU 2.11 to units with serial number H213D304505800 and below. If MCU 2.11 is inadvertently loaded to units with serial number H213D304505800 and below, this will result to your D3045 having no audio output. If this happens, reload again MCU 2.07 to the affected unit.

MCU 2.11

MCU 2.11 is a software release to support the use of an alternative DAC IC.

MCU 2.11 is applicable only to units from the following serial number

- From H213D304505801 and higher

IMPORTANT!
Do not to load MCU 2.07 to units with serial number from H213D304505801. If MCU 2.07 is inadvertently loaded to units with serial number from H213D304505801, this will result to your D3045 having no audio output. If this happens, reload again MCU 2.11 to the affected unit.

BT 0.23

BT 0.23 is the latest BT firmware maintenance release. This can be loaded to all D3045 units and not affected by above MCU firmware limitations.