



# C368 SOFTWARE UPDATE NOTES

## MCU 1.75 VFD 1.22 BT 1.26

---

MCU 1.75 VFD 1.22 BT 1.26 are applicable only for the following serial numbers

- Up to H217C368G27633 including H217C368G27637, ...27634, ...27659, ...27636 and ...27635

### IMPORTANT!

- DO NOT load MCU 2.02 VFD 2.01 BT 1.26 to units up to H217C368G27633. If VFD 2.01 is inadvertently loaded to units up to H217C368G27633 (including the serial numbers mentioned above), the unit will decline the VFD upgrade file, or the display will show "USB Upgrade Fail". Loading MCU 2.02 will go through but should not be implemented. Ensure that MCU 1.75 VFD 1.22 BT 1.26 are loaded for units up to serial number H217C368G27633.