



C388 SOFTWARE UPDATE NOTES

MCU 2.02 VFD 2.01 BT 1.26

MCU 2.02 VFD 2.01 BT 1.26 and their future iterations are applicable only for the following serial numbers

- **From** H216C388G12243 **excluding** H216C388G12250, ...12260 and ...12744

IMPORTANT!

- **DO NOT load MCU 1.75 VFD 1.22 BT 1.26 to units from H216C388G12243.** If MCU 1.75 VFD 1.22 are inadvertently loaded to units from H216C388G12243 (including the exclusions mentioned above), the front panel display may go dark. If this happens, follow the Guidelines on how to recover front panel display when wrong firmware is installed (Service Hint - C368_C388-HINT2021-01).