



# C388 SOFTWARE RELEASE NOTES

## MCU 1.74

---

C388 software update MCU 1.74 is a maintenance release that includes the following change:

- Firmware support for MDC USB DSD\*

*\* Applies to units with the optional MDC USB DSD module installed*

## Software Package

---

C388 MCU 1.74 software package includes the following software version details:

- Main : V1.74

*It is not necessary to upgrade VFD and BT software versions as they remain the same.*

- VFD : V1.22
- BT : V1.26