



C388 SOFTWARE UPDATE NOTES

MCU 1.75 VFD 1.22 BT 1.26

MCU 1.75 VFD 1.22 BT 1.26 are applicable only for the following serial numbers

- Up to H216C388G12242 including H216C388G12250, ...12260 and ...12744

IMPORTANT!

- DO NOT load MCU 2.02 VFD 2.01 BT 1.26 to units up to H216C388G12242. If VFD 2.01 is inadvertently loaded to units up to H216C388G12242 (including the serial numbers mentioned above), the unit will decline the VFD upgrade file, or the display will show "USB Upgrade Fail". Loading MCU 2.02 will go through but should not be implemented. Ensure that MCU 1.75 VFD 1.22 BT 1.26 are loaded for units up to serial number H216C388G12242.